




# Banteay Chhmar Cambodia

## Site Map - Conservation & Planning



### Map Legend

- Ancient Khmer Temple
- Archaeological Feature
- Satellite Imagery (April 24, 2009)



1:1,500



### Emergency Conservation of Face Tower # 18

Following the serious damage to Tower 18 after the heavy 2009 monsoon season, GHF enacted emergency measures to record, dismantle, repair, consolidate and reassemble the ancient structure.



### Primary GHF Conservation Area

Work on the reconstruction of the bas-relief wall in the southeast corner of the central temple complex is under way, with trained local workers recording, repairing and consolidating the carved stone blocks prior to their being reset in their original positions.



### GHF Stone Conservation Staging Areas

### Looting

A large portion of the SW wall was removed in 1998 by looters for their intricately carved bas-reliefs.

